

SUPPLEMENT 1-5

TO

Actions for the Pallinup: Middle Pallinup Floodway Condition Survey **Report prepared by Steve & Geraldine Janicke NSPNR November 2017**

Pallinup River 2001-2017 Photo Audit Comparison

Images PAL100 - PAL119

Tambellup - Gnowangerup Rd to Chester Pass

The initial reconnaissance was undertaken by Steve Janicke and Travis Drysdale. The information was used to make an assessment about the general ecological condition of the river and what management issues were relevant. The photo audit provided a rapid assessment that could be repeated at a later date to track changes in the river condition. Several sites were revisited after a moderate flood that same year and this confirmed that the photo points could provide a valid measure of environmental change.

Label description

Photo Point ID	Date	Easting	Northing
----------------	------	---------	----------

Note all coordinates are in Zone 50 and the datum is WGS84 equivalent to GDA95.

This project received funding from the Western Australian Government's State NRM Program, supported by Royalties for Regions program. The project title is: *Actions for the Pallinup; Demonstrating Improvements in Water Condition*. Community Action Grant 2016 - A16005.



natural resource
management program



Supported by Royalties for Regions



SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL100



PALL100	25-October-2001	597894	6231375	50
---------	-----------------	--------	---------	----



PALL100	09-September-2017	597894	6231381	
---------	-------------------	--------	---------	--

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL101



PALL101	25-October-2001	598515	6231311
---------	-----------------	--------	---------



PALL101	09-September-2017	598514	6231320
---------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL102



PALL102	25-October-2001	598670	6231242
---------	-----------------	--------	---------



PALL102	09-September-2017	598664	6231247
---------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL103



PALL103	25-October-2001	598721	6231104
---------	-----------------	--------	---------



PALL103	09-September-2017	598723	6231104
---------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL104



PALL104	25-October-2001	598880	6230967
---------	-----------------	--------	---------



PALL104	09-September-2017	598870	6230985
---------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL105



PALL105	25-October-2001	599143	6230397
---------	-----------------	--------	---------



PALL105	09-September-2017	599156	6230409
---------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL106



PALL106	25-October-2001	600222	6230440
---------	-----------------	--------	---------



PALL106	09-September-2017	600231	6230454
---------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL107



PALL107	25-October-2001	600462	6230312
---------	-----------------	--------	---------

Kalynda Pool



PALL107	12-September-2017	600464	6230309
---------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL108



PALL108	25-October-2001	600536	6230193
---------	-----------------	--------	---------



PALL108	12-September-2017	600515	6230188
---------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL109



PALL109	25-October-2001	600694	6230009
---------	-----------------	--------	---------



PALL109	12-September-2017	600691	6230016
---------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL110



PALL110	25-October-2001	600961	6229931
---------	-----------------	--------	---------



PALL110	12-September-2017	600963	6229929
---------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL110A



PALL110A	25-October-2001	600961	6229931
----------	-----------------	--------	---------



PALL110a	12-September-2017	600965	6229926
----------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL111



PALL111	25-October-2001	601263	6230013
---------	-----------------	--------	---------



PALL111	12-September-2017	601266	6230016
---------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL112



PALL112	25-October-2001	601718	6229963
---------	-----------------	--------	---------

y



PALL112	12-September-2017	601706	6229970
---------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL113



PALL113	25-October-2001	601821	6229993
---------	-----------------	--------	---------



PALL113	12-September-2017	601830	6230005
---------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL114



PALL114	25-October-2001	602418	6230514
---------	-----------------	--------	---------



PALL114	12-September-2017	602423	6230496
---------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL115



PALL115	25-October-2001	602803	6230507
---------	-----------------	--------	---------



PALL115	12-September-2017	602800	6230514
---------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL116



PALL116	25-October-2001	602865	6230294
---------	-----------------	--------	---------



PALL116	12-September-2017	602856	6230298
---------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL117



PALL117	25-October-2001	602903	6230223
---------	-----------------	--------	---------



PALL117	12-September-2017	602907	6230221
---------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL118



PALL118	26-October-2001	603204	6230219
---------	-----------------	--------	---------



PALL118	12-September-2017	603188	6230212
---------	-------------------	--------	---------

SUPPLEMENT 1-5. Pallinup River 2001-2017 Photo Audit Comparison PAL100 - PAL11

PALL119



PALL119	26-October-2001	603326	6230192
---------	-----------------	--------	---------



PALL119	12-September-2017	603321	6230193
---------	-------------------	--------	---------