

SUPPLEMENT 1-6
TO
Actions for the Pallinup: Middle Pallinup Floodway Condition Survey
Report prepared by Steve & Geraldine Janicke NSPNR November 2017

Pallinup River 2001-2017 Photo Audit Comparison

Images PAL120 - PAL139

Tambellup - Gnowangerup Rd to Chester Pass

The initial reconnaissance was undertaken by Steve Janicke and Travis Drysdale. The information was used to make an assessment about the general ecological condition of the river and what management issues were relevant. The photo audit provided a rapid assessment that could be repeated at a later date to track changes in the river condition. Several sites were revisited after a moderate flood that same year and this confirmed that the photo points could provide a valid measure of environmental change.

Label description

Photo Point ID	Date	Easting	Northing
----------------	------	---------	----------

Note all coordinates are in Zone 50 and the datum is WGS84 equivalent to GDA95.

This project received funding from the Western Australian Government's State NRM Program, supported by Royalties for Regions program. The project title is: *Actions for the Pallinup; Demonstrating Improvements in Water Condition*. Community Action Grant 2016 - A16005.



natural resource
management program



Supported by Royalties for Regions



Steve & Geraldine Janicke

SUPPLEMENT 1-6 Pallinup River 2001-2017 Photo Audit Comparison PAL120 - PAL139

PALL120



PALL120	26-October-2001	603599	6229867
---------	-----------------	--------	---------



PALL120	12-September-2017	603583	6229872
---------	-------------------	--------	---------

PALL121



PALL121	26-October-2001	603887	6229779
---------	-----------------	--------	---------



PALL121	12-September-2017	603884	6229785
---------	-------------------	--------	---------

SUPPLEMENT 1-6 Pallinup River 2001-2017 Photo Audit Comparison PAL120 - PAL139

PALL122



PALL122	26-October-2001	604133	6229713
---------	-----------------	--------	---------



PALL122	12-September-2017	604121	6229716
---------	-------------------	--------	---------

PALL123



PALL123	26-October-2001	604114	6229362
---------	-----------------	--------	---------



PALL123	13-September-2017	604112	6229363
---------	-------------------	--------	---------

PALL124



PALL124	26-October-2001	604214	6229272
---------	-----------------	--------	---------



PALL124	13-September-2017	604208	6229279
---------	-------------------	--------	---------

PALL125



PALL125	26-October-2001	604420	6229195
---------	-----------------	--------	---------



PALL125	13-September-2017	604410	6229196
---------	-------------------	--------	---------

PALL126



PALL126	26-October-2001	604613	6229061
---------	-----------------	--------	---------



PALL126	13-September-2017	604608	6229061
---------	-------------------	--------	---------

SUPPLEMENT 1-6 Pallinup River 2001-2017 Photo Audit Comparison PAL120 - PAL139

PALL127



PALL127	26-October-2001	604931	6229110
---------	-----------------	--------	---------



PALL127	13-September-2017	604927	6229166
---------	-------------------	--------	---------

PALL128



PALL128	26-October-2001	605545	6228968
---------	-----------------	--------	---------



PALL128	13-September-2017	605534	6228965
---------	-------------------	--------	---------

PALL129



PALL129	26-October-2001	605626	6228873
---------	-----------------	--------	---------



PALL129	13-September-2017	605585	6228878
---------	-------------------	--------	---------

PALL130



PALL130	26-October-2001	606092	6228801
---------	-----------------	--------	---------



PALL130D	13-September-2017	606087	6228814
----------	-------------------	--------	---------

PALL131



PALL131	26-October-2001	606612	6228819
---------	-----------------	--------	---------



PALL131	13-September-2017	606606	6228824
---------	-------------------	--------	---------

PALL132



PALL132	26-October-2001	606803	6228774
---------	-----------------	--------	---------

2017 - Photo Point omitted (Canola crop)

PALL133



PALL133	26-October-2001	607292	6229021
---------	-----------------	--------	---------



PALL133	13-September-2017	607301	6229026
---------	-------------------	--------	---------

SUPPLEMENT 1-6 Pallinup River 2001-2017 Photo Audit Comparison PAL120 - PAL139

PALL134



PALL134	26-October-2001	607527	6228977
---------	-----------------	--------	---------



PALL134	13-September-2017	607526	6228976
---------	-------------------	--------	---------

PALL135



PALL135	26-October-2001	607739	6228979
---------	-----------------	--------	---------



PALL135	13-September-2017	607747	6228984
---------	-------------------	--------	---------

PALL136



PALL136	26-October-2001	608003	6229027
---------	-----------------	--------	---------



PALL136	13-September-2017	608005	6229024
---------	-------------------	--------	---------

PALL137



PALL137	26-October-2001	607989	6228673
---------	-----------------	--------	---------



PALL137	14-September-2017	607992	6228673
---------	-------------------	--------	---------

PALL138



PALL138	26-October-2001	608260	6228335
---------	-----------------	--------	---------



PALL138	14-September-2017	608233	6228347
---------	-------------------	--------	---------

PALL139



PALL139	26-October-2001	608426	6228151
---------	-----------------	--------	---------



PALL139	14-September-2017	608424	6228154
---------	-------------------	--------	---------